Council of Construction Associations #138 - 5751 Cedarbridge Way, Richmond, B.C. V6X 2A8 Telephone (604) 241-7667 Fax (604) 241-7678

email: grantmcmillan@shaw.ca

Grant McMillan, President

Please post or distribute this important information on injuries/incidents.

CONSTRUCTION

Injury Type: Fatal

Core Activity: Rock scaling Location: Lower Mainland ID Number: 2009113820050 Date of Accident: 2009-Feb

Young worker (ages 15-24)

Worker's experience at this task is unknown

During scaling activities, a rock fatally struck a young worker.

Injury Type : Contusions, stiffness Core Activity : Electrical work Location : Central Interior

ID Number : 2009112850045 Date of Accident : 2009-Feb

Young worker (ages 15-24)

More than 2 years' experience at this task

As a young worker descended a set of stairs, the stairs dislodged from both the upper and lower attachment points. The worker fell 15 feet down the stairwell. The stairs had been detached in preparation for

removal and replacement but no effective guarding was in place to prevent inadvertent use.

.....

Injury Type: Lacerated fingers
Core Activity: Building construction

Location: Vancouver Island ID Number: 2009137290035 Date of Accident: 2009-Feb

A worker's fingers were lacerated as he used an angle grinder to cut along the perimeter of a window frame.

See a hazard alert about another incident involving an angle grinder: http://www2.worksafebc.com/Publications/Posters.asp?ReportID=34966

Injury Type: Cracked rib

Core Activity: Steel building work

Location: Lower Mainland ID Number: 2009157530038 Date of Accident: 2009-Feb

A worker was tied to a steel structure while working on a roof. The structure fell away from the building and the worker was pulled off the building. The worker fell 43 feet and landed in a fresh excavation pile.

Injury Type: Fractured foot, lacerations

Core Activity: Low slope roofing

Location: Lower Mainland ID Number: 2009163710031 Date of Accident: 2009-Feb

A worker was relocating a 100-foot propane hose (attached to a portable torch) on a roof. The worker tripped, fell through the plastic pane of the skylight, and landed on the floor about 19 feet below.

Injury Type: Injuries to ankle and back Core Activity: Installation of roof vents

Location: Central Interior ID Number: 2009116120031 Date of Accident: 2009-Feb

A worker was installing vents on a roof with a pitch of 8/12. He slid off the roof and fell a total distance of about 32 feet from the roof peak to the ground. The workplace did not have the required written fall protection plan.

.....

Injury Type: Swelling

Core Activity: Operation of front-end loader

Location: Lower Mainland ID Number: 2009163640039 Date of Accident: 2009-Feb

A front-end loader was scraping debris from a paved road. The leading edge of the bucket struck a catch basin, jarring the machine and causing the operator to strike his head inside the cab.

Injury Type: Multiple fractures
Core Activity: Stringing pipe

Location : Northern BC

ID Number : 2009144250021 Date of Accident : 2009-Feb

Workers were laying 24-inch-diameter pipe using a pipeline side boom unit. As the side boom moved forward to get a shorter piece of pipe off a tractor-trailer, its rear lifting hook inadvertently caught a longer piece of pipe. The longer pipe was pulled forward, pinning a worker against the bulkhead of the tractor-trailer unit.

Injury Type: Close call

Core Activity: Tower crane operation

Location: Lower Mainland

ID Number : 2009114550024 Date of Accident : 2009-Jan

A tower crane was discovered to have a large crack (3 to 5 feet long) in the welded connection of the ring gear mounting flange just behind the turntable bolts.

Injury Type: Close call

Core Activity: Avalanche control

Location : Central Interior ID Number : 2009163050023 Date of Accident : 2009-Jan

An avalanche control blast was set off at a ski hill operation. The blast damaged a lift operator's shack 40 metres away, but the three workers inside the shack were not injured. The blaster had underestimated the blast concussion that would result from the amount of explosive used.

Injury Type: Eye injury
Core Activity: Framing
Location: Central Interior
ID Number: 2009112850005
Date of Accident: 2009-Jan

A framer was working above another worker. A nail from the framer's nail gun deflected and struck the worker below him.

See a bulletin about preventing injuries from nail guns:

http://www2.worksafebc.com/Publications/Posters.asp?ReportID=34835

Injury Type : Close call

Core Activity: Mobile crane operation

Location: Vancouver Island ID Number: 2009118870084 Date of Accident: 2009-Jan

At a construction site, a mobile crane was placing a load when the

operator heard a noise. Subsequent inspection of the boom revealed a structural failure of about 2 inches by 22 inches at the edge of the welded boom.